

## APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018

Path name	Inspector	Reg used Y/N	Cond'n G,Av,P	hazards	features (on routes)	action required	grid refs	picture(s)
Blakenhall FP1	Chris K	N	A	stiles broken at 723 476 tractor damage, overgrown , fallen trees left of pond p2	see photo	fix hazards	723 476	Tree across path
Blakenhall FP2	Chris K	N	P					
Blakenhall FP3	Chris K	N	P	no stile at Blakenhall Farm, permissive path not used		fix hazards	72398-47365	
Blakenhall FP4	Chris K	S	G	south end				
Blakenhall FP4	Chris K	S	A	north end overhanging branches at start	see photo	fix hazards	73083-47585	Overgrown
Blakenhall FP5	Chris K	N	A	stile collapsed 731-471. no sign at 727 472, diverted round paddock at hayes Farm		fix hazards	731-471 and 727-472	
Blakenhall FP6	Chris K	Y	G					
Blakenhall FP7	Chris K	N	P	stile broken 730 485		fix hazards	730-485	
Blakenhall FP9	Chris K	Y	A					
Blakenhall FP10	Chris K	N	A	no stile across hedge, just after start		fix hazards	72308-47835	
Blakenhall FP11	Chris K	S	P	no path across maize, stile collapsed at 727 494		fix hazards	727-494	
Blakenhall FP13	Chris K	Y	G					
Blakenhall FP17	Chris K /Bob F	Y	A	stile broken 745 469 , no hedge there anyway	see photo	fix hazards	727-469	Pick up the pieces of broken stile
Blakenhall BR12	Chris K	Y	G					
Blakenhall BR8	Chris K	N	G	tarmac to Farm- part of way				

**APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018**

Bridgemere FP1	Chris K /Bob F	N	G					
Bridgemere FP10	Chris K /Bob F	N	G	great views of the Bickerton hills and in the opposite direction Mow Cop, Croker Hill and Buxton hills	see photo			Bickerton Hills
Bridgemere FP3	Chris K /Bob F	N	G					
Bridgemere FP4	Chris K /Bob F	N	G	gate triple chained onto a51		fix hazards	72018-45123	
Bridgemere FP5	Chris K /Bob F	N	G					
Bridgemere FP6	Chris K /Bob F	N	G	maize blocking path, easy diversion made great views of the Bickerton hills and the Berwyns beyond				
Bridgemere FP7	Chris K /Bob F	N	G	poorly marked to Yew Tree lane		fix hazards	72290-44470	
Bridgemere FP8	Chris K /Bob F	N	G					
Bridgemere FP9	Chris K /Bob F	N	G					
Checkley FP1	Chris K	N	P	fallen small tree blocking path by checkly lane, some clearing at stile needed.	this path feeds a permissive path to Blakenhall	fix hazards	see photos73303-46208	Overgrown and Tree blocking stile
Checkley FP2	Chris K /Bob F	N	A	obstructed by electric fences		fix hazards	72710-45558	
Checkley FP3	Chris K /Bob F	N	A	obstructed by electric fences		fix hazards	72683-45645	
Checkley FP4	Chris K	Y	G					

## APPENDIX L(2) Wyburnury Combined Parishes NP PROW Inspection 2017-2018

Checkley FP5	Chris K	Y	G	diverted round Roadside house				
Checkley FP7	Chris K	N	G	straight throu Farm drive				
Checkley FP8	Chris K	Y	A	no sign at south end of bridleway	photos bridge over stream	fix hazards	see photos 74395-45690	No sign
Checkley FP9	Chris K	Y	G	path now walked at side of pond	photo			see ponds and Maize
Checkley FP13	Chris K	N	P	has been diverted to county boundary no stile found		better signage	73953-44535	
Checkley FP14	Chris K	N	P		to abandoned Farmhouse			
Checkley FP15	Chris K	N	P	bulldozed land path non existant				No Markers
Checkley FP16	Chris K	N	G					
Checkley FP17	Chris K	Y	G					
Checkley BR6	Chris K	N	G	tarmac half way				
Chorlton FP1	Matthew P	S	A	long fields, spread out signs. very overgrown area south end (250m)		better signage	72763-49400	
Chorlton FP3	Matthew P	Y	G	bridge over train line. stile in poor condition where it meets the Road		fix hazards	72615-50602	
Chorlton FP4	Matthew P	N	G	well signposted, but not close to other footpaths				
Chorlton FP6	Chris K	N	P	as Blakenhall FP7				
Chorlton FP7	Matthew P	Y	P	stiles broken, 2 wooden bridges in need of repair	see photos (SCW CNCR)	fix hazards	72313-50975	Bridges and Mud
Chorlton FP8	Matthew P	N	P	numerous collapsed and damaged stiles	see photos	fix hazards	71870-51090	and views

## APPENDIX L(2) Wyburnury Combined Parishes NP PROW Inspection 2017-2018

Chorlton FP9	Matthew P	Y	P	signage good, dense overgrowth in one section	see photos	fix hazards	72403-51027	overgrown
Chorlton FP10	Matthew P	Y	G	runs through wychwood estate and signs difficult to follow at times		better signage	72903-50840	
Chorlton FP11	Matthew P	Y	G	a short footpath	see photo			kissing gate
Chorlton FP12	Matthew P	Y	G	parts are on wooden boards next to 2 ponds (1 large. 1 small)	see photos			Wildlife and bog
Chorlton FP13	Matthew P	Y	G	a short footpath (tunnel under railway line to FP12)	see photos			Underpass of the West Coast Main Line
Chorlton FP14	Matthew P	Y	G	small, end of FP9				
Chorlton FP15	Matthew P	Y	G	small, end of Hough FP7				
Chorlton FP16	Matthew P	Y	G	trail path through wooded area				
Chorlton FP17	Matthew P	Y	G	short footpath linking to FP11				
Chorlton BR2	Chris K	Y	G	most of it is cyclable				
Chorlton BR5	Chris K	N	P	non existent east of mere gutter, saplings in path at county boundary		fix hazards	74313 48710	x3 no Bridle way
Hatherton FP1	Bryan C	Y	G	damaged gate at SJ67015 48360 damaged foot bridge at SJ67015 48360	none	fix hazards	SJ67015 48360	from Audlem Road to footbridge at cp boundary
Hatherton FP2	Bryan C	Y	G	access limited by electric fences	none	fix hazards	68053-48663	from style at cp boundary to Audlem Road

**APPENDIX L(2) Wyburnury Combined Parishes NP PROW Inspection 2017-2018**

Hatherton FP3	Bryan C	Y	G	repair or replacement required for stile at SJ 68405 48480	none	fix hazards	SJ 68405 48480	from Park Lane to stile at cp boundary
Hatherton FP4	Bryan C	Y	G	none	none			from Park Lane to Crewe Road
Hatherton FP5	Bryan C	N	P	broken stiles at SJ 68540 47398	dangerous access to footpath at sw end of footpath at SJ68480 47265  I would recommend that this footpath is removed from the network as it serves no purpose and the dangerous access could cause accidents	fix hazards, consider diversion to Oakes Corner as discussed	SJ 68540 47398 and SJ68480 47265	from Crewe Road to Park Lane
Hatherton FP6	Bryan C	Y	G	none	none			from Park Lane to Crewe Road
Hatherton FP7	Bryan C	Y	G	no footpath sign at south end of footpath (Hunsterson Road) at SJ69045 47433	none	better signage	SJ69045 47433	from Crewe Road to Hunsterson Road
Hatherton FP8	Bryan C	Y	A	no waypoint markers on changed routing around helers factory	footpath has been rerouted on definitive map and on Road but not on os map.	better signage and possible reroute- landowner wants to revert back to route along edge of field.	68820 47268 and 68723 47260	from Crewe Road to Hunsterson Road
Hatherton FP9	Bryan C	Y	G	none	joins with FP12 (South Cheshire way)			from Hunsterson Road to FP 13

**APPENDIX L(2) Wyburnbury Combined Parishes NP PROW Inspection 2017-2018**

Hatherton FP10	Bryan C	N	G	none	<b>i would recommend that this footpath is removed from the network. it serves no purpose as it goes nowhere</b>	remove from map	68158-46753	from Audlem Road to birchall moss
Hatherton FP11	Bryan C	Y	G	none	none			from Audlem Road to footbridge at cp boundary, No stile and broken gate photo
Hatherton FP12	Bryan C	Y	G	none	South Cheshire way			from cp boundary to Hunsterson Road
Hatherton FP13	Bryan C	Y	G	none	shown as a dead end but actually continues to join FP 14 (South Cheshire way) at footbridge at cp boundary	remap	69648-47575	scenic from footbridge at cp boundary to unnamed Road
Hatherton FP14	Bryan C	Y	G	none	South Cheshire way			from Hunsterson Road to footbridge at cp boundary
Hatherton FP15	Bryan C	Y	G	none	South Cheshire way			from Audlem Road to bridge at cp boundary
Hough FP6	Nigel D	Y	A	none	short path. pasture with horses. 3 stiles.	signpost at side of newcastle Road Leaning.	71345 51160	FP06 oly_20171120_pb201790.jpg
Hough FP7	Nigel D CK	N	P	on re-examining this section, i found the point at SJ 71644 49829 where i should have crossed into a parallel field. this is signed and has a stile. from the eastern end, the path is concealed by woodland at SJ 71860 49927.	pasture with cattle. path ends on parish boundary with Chorlton.	some additional signage, especially at the eastern end of the parallel section described under "hazards", would be advantageous.	71860 49927.	FP07 oly_20171120_pb201766.jpg

## APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018

Hough FP8	Nigel D	Y	G	none, noting there is another path around the moss onto birch lane which is waymarked off FP8	metalled in part. used by house occupants as drive. work was being carried out at the time putting down hardcore on the path. (CNCR, WTP, SCW, 2SW)		71635 60670	FP08 oly_20171118_pb181661.jpg
Hough FP9	Nigel D CK	N	A	large badger sett at SJ 71515 49307 (visible on google earth!). very rough ground.	pasture with cattle. (SCW)	path around area of badger sett needs to be checked for trip hazards.	71515 49307	FP09 oly_20171120_pb201759.jpg, FP09 oly_20171120_pb201760.jpg
Hough FP10	Nigel D	N	A	none	pasture with cattle.			
Hough FP11	Nigel D	N	A	stile broken on border with Chorlton	pasture with cattle. parallel to railway but no appreciable noise from the railway services.	stile broken at SJ 72759 49387	72759 49387	FP11 oly_20171120_pb201780.jpg
Hough FP12	Nigel D	N	A	none	tarmac drive to house. (SCW)			
Hough FP12A	Nigel D	N	G	none	pasture used as dog training area. path zigzags around the perimeter of the fields following realignment some time recently. (SCW)			
Hough FP13	Nigel D	Y	A	narrow path runs close to edge of ditch. no action required except to keep it weedfree.		path needs to be kept weedfree.	71265 51307	FP13 oly_20171120_pb201786.jpg

**APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018**

Hough FP14	Nigel D	N	G	none, mud	pasture. very muddy at junction with FP15 but hard surface below mud. electric fences across path but with proper means to allow safe passage.			
Hough FP14A	Nigel D	N	Av	none	pasture. adjacent to field/Road boundary.			
Hough FP15	Nigel D	H	G	none	tarmac drive to Farm.		Cobb's Lane to Dove House Farm	
Hough FP16	Nigel D	S	A	animal burrow creates hazard at SJ 70784 50589. mud in field with logs laid by walkers (slippery) at SJ 71173 50438.	pasture. some parts regularly used, others not. (WTP, CNCR, 2SW)	burrow needs to be filled or fenced as it is directly in line of walking.	70784 50589 SJ 71173 50438	FP16 oly_20171118_pb181653.jpg, FP16 oly_20171118_pb181655.jpg
Hough FP17	Nigel D	S	A	none	pasture. parts nearer to Wybunbury more heavily used. new fence being made across path at around SJ 70320 50241 but gap left for stile. (2SW)		70320 50241	FP17 oly_20171118_pb181681.jpg
Hough FP18	Nigel D	S	A	none	pasture with cattle and sheep.			
Hough FP21	Chris K	Y	P	muddy, lots of dog muck,	opposite Cockshades diverted and skirts building site 102m long	dog fouling signs up, possible bin on stock lane, redirect arrow signs from lane	69868 50907	



## APPENDIX L(2) Wyburnury Combined Parishes NP PROW Inspection 2017-2018

Hough FP22	Nigel D	H	G	none	tarmac.	fix fallen finger post	69838 50815	
Hough FP23	Nigel D	N	G	none	pasture.			
Hunsterson FP2	Bob F	Y	G	see note on FP14				
Hunsterson FP3	Bob F	N	G					
Hunsterson FP4	Bob F	N	G					
Hunsterson FP5	Bob F	N	G	marker from FP4 would help		better signage	69460 45803	
Hunsterson FP6	Bob F	N	G	2nd stile near whittakers green lane overgrown, fence removed at side		fix hazards	69435 45818	
Hunsterson FP7	Bob F	N	G					
Hunsterson FP8	Bob F	N	A	obstructed by fallen tree at Birchall Brook		fix hazards	69578 444405	
Hunsterson FP9	Bob F	N	G					
Hunsterson FP10	Bob F	N	G					
Hunsterson FP11	Bob F	N	G	some marker help needed at Pewit Lane end		better signage	70058-45420	
Hunsterson FP12	Bob F	N	G	some marker help needed at Malt Kiln Farm		better signage	70095-45370	
Hunsterson FP14	Bob F	Y	G	if north end Bearcat Fields gates are closed, the side route is obstructed and stile is broken	(SCW)	fix hazards	69218-46375	
Hunsterson FP15	Bob F	N	G					

**APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018**

Hunsterson FP16	Bob F	N	G	markers required at old Farmhouse and it is not clear through Plover's Rise (it also says permitted path). markers required beyond Plover's Rise to Birchall Brook - signs around Birchall Brook at this point do not indicate all footpaths.		better signage	69373-45535	
Hunsterson FP17	Bob F	N	G					
Hunsterson FP22	Bob F	N	G					
Lea FP2	Chris K	N	P	routed along quarry truck track + another path across quarry is way marked but blocked by		better signage	70463 48708	Quarry Antiques
Lea FP3	Chris K	Y	G	SCW	(SCW)			
Lea FP4	Chris K	N	G	SCW	(SCW)			
Lea FP5	Chris K	N	P	muddy				
Lea BR6	Chris K	Y	G	just about cyclable	(SCW)			
Walgherton FP1	Chris K	N	G		views of the cliffs and Wybunbury hollow			
Walgherton FP3	Chris K	Y	G		SCW track t a51			
Walgherton FP4	Chris K	Y	G		good views of Wybunbury church from Oat Eddish			
Walgherton FP5	Chris K	N	P	muddy	scenic along brook			
Walgherton FP6	Chris K	Y	G		views of tower out of wybun			
Walgherton FP7	Chris K	Y	G		out of Wybunbury			
Walgherton FP9	Chris K	Y	G		past Oat Eddish			

## APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018

Walgherton FP10	Chris K	Y	G		Farm drive			
Walgherton FP13	John S	N	P	diverted to nowhere, stile in wood in bad condition	back lane see Wybunbury FP3	see photo with gridref		Wrong direction arrow
Walgherton BR8	Chris K	Y	G	tarmac Road to quarry, hazards are the trucks	(SCW)			
Wybunbury FP1	John S	y	G		through tower churchyard	is in 2 parts 1km apart total length is 666m as defined on the path summary - the grid reference so calculated is meaningless.		
Wybunbury FP1	John S, CK	S	A		by fishing pool			
Wybunbury FP2	John S, CK	Y	G	not way marked, there are 2 parts to FP2 either side of Wrinehill Rd, a long way apart!!		is in 2 parts 500m apart total length is 214m as defined on the path summary - the grid reference so calculated is meaningless. signage reqd.north part.	70128-49895	
Wybunbury FP3	John S,	n	P	not in existence sign post points to Walgherton FP12	(SCW)	bring into existance	70385-49328	Bulldozered away FP3
Wybunbury FP4	John S	y	G	none	Wybunbury moss circular walk			

**APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018**

Wybunbury FP5	John S,	y	A	none	this path is west of Cockshades Farm (CNCR)			
Wybunbury FP6	John S	Y	A	barbed wire fence across route		fix hazards	69625-50458	
Wybunbury FP7	John S	Y	A	none	(CNCR)			
Wybunbury FP8	John S	Y	A	none	lovely walk across bridge over Wybunbury brook			
Wybunbury FP9	John S	y	A	none	nice walk down to the brook			
Wybunbury FP10	John S	y	A	none	(CNCR)			
Wybunbury FP11	John S	y	A	muddy	Wybunbury moss circular walk			
Wybunbury FP12	John S	N	P	does not exist	should join onto Wybunbury FP 3	remove from map	6931-4966	
Wybunbury FP13	John S	Y	A	none	Wybunbury moss circular walk (CNCR)			
Wybunbury FP14	John S	Y	A	none				
Wybunbury FP15	John S	y	G	none				
Wybunbury FP16	John S	y	P	muddy	skirts a building site , temporary route			
Wybunbury FP19	Nigel D John S	Y	G	none	pasture but with gravel path along boundary to Cockshades Farm. path crosses caravan store at Cockshades Farm.	check sign has not been removed at approx. SJ 70102 50495 more in Hough parish than Wybunbury assumed wrongly named as Wybunbury	70102 50495	FP19 oly_20171118_pb181639.jpg

**APPENDIX L(2) Wybunbury Combined Parishes NP PROW Inspection 2017-2018**

Wybunbury FP20	Nigel D John S	S	P	muddy	pasture for horses with new stiles in the fences. (WTP, CNCR, 2SW)	more in Hough parish than Wybunbury assumed wrongly named as Wybunbury		
----------------	-------------------	---	---	-------	--	---	--	--